TOP SECRET

CONTROL NO.

BYE 2810-65

Copy 10

REFERRED TO	RECEIVED			RELEASED		SEEN BY	
OFFICE	SIGNATURE	DATE	TIME	DATE	TIME	NAME & OFFICE SYMBOL	DATE
D/TECH/C	<i>Job 7Ф</i> В	Ø4 Sla	57 / e/				

Handle Via Indicated Controls

BYEMAN

Access to this document will be restricted to those persons cleared for the specific projects;

OXCART	······	• • • • • • • • • • • • • • • • • • • •
•••••		••••••••

WARNING

This document contains information affecting the national security of the United States within the meaning of the espionage laws U. S. Code Title 18, Sections 793 and 794. The law prohibits its transmission or the revelation of its contents in any manner to an unauthorized person, as well as its use in any manner prejudicial to the safety or interest of the United States or for the benefit of any foreign government to the detriment of the United States. It is to be seen only by personnel especially indoctrinated and authorized to receive information in the designated control channels. Its security must be maintained in accordance with regulations pertaining to BYEMAN Control System.

J-88 Hd 65'

TOP SECRET

GROUP 1
Excluded from automatic
downgrading and declassification

TOP SICKET



CENTRAL INTELLIGENCE AGENCY

EO 12958 6.2(c) 2 0 AUG 1965

EO 12958

3.3(b)(1) > 25 Yrs

WASHINGTON 25, D. C.

OFFICE OF THE DIRECTOR

BYE-2810-65 Copy /O

MEMORANDUM FOR THE PRESIDENT

On 14 August 1965, an A-12 aircraft flew nonstop from to Orlando, Florida, back to the Test Site, then to Kansas City and return to its base. The flight was accomplished exactly as planned, simulating an operational mission with two air refuelings and three cruise legs. On each leg of the mission the aircraft cruised at its designed operational speed of Mach 3. 1 at altitudes between 80,000 and 90,000 feet. The flight covered a total distance of 6500 nautical miles in 5 hours and 27 minutes, including air refueling times. A total time of 2 hours and 20 minutes was flown at cruise speed of Mach 3. 1. The aircraft landed in excellent condition with only three minor malfunctions.

The significant aspects of this flight are:

- 1. There were no air-flow disturbance conditions encountered in the engine air inlets--not even minor roughness. (This is the classic problem that plagues supersonic speed turbojet aircraft).
 - 2. There were no electrical system problems.
- 3. There were no heat problems to the aircraft engines, or pilot due to the prolonged high speed, high temperature flight.
- 4. This flight is an important milestone and increases our confidence that we should have a reliable, operational aircraft in near future. (3 to 6 months for further validation.)

(signed) W. F. Raborn

W. F. RABORN

APPROVED FOR RELEASE DATE: AUG 2007

HANDLE VIA BYEMAN CONTROL SYSTEM

GROUP 1
Excluded from automatic
dewngrading and
declassification

TOP SECRET

BYE-2810-65 Page 2

Signature Recommended:
Director of Office of Special Activities
Signature Recommended:
2.6
Deputy Director for Science and Technology

HANDLE VIA BYEMAN CONTROL SYSTEM

JOP SECRET

BYE-2810-65 Page 3

Distribution:

Copy 1 - Addressee

Copy 2 - DCI

Copy 3 - DDCI

Copy 4 - Ex. Dir. - Compt.

Copy 5 - ER

Copy 6 - DD/S&T

Copy 7 - DD/S&T

Copy 8 - DD/S&T

Copy 9 - D/OSA

Copy 10 - D/TECH

Copy 11 - PS/OSA

Copy 12 - SS/OSA

Copy 13 - D/FA/OSA

Copy 14 - OXC/OSA

Copy 15 - SAL/OSA

Copy 16 - RB/OSA

D/OSA/JCLedford/mcm(19 Aug 65)

HANDLE VIA BYEMAN CONTROL SYSTEM

TOD COOPE